





Parts List



A x 3



B x 3




C x 12




D x 12

Installation Guide


1



2



3



CAUTION

Please power off the PC and check the Positive and Negative ends on the connector before connecting the cable to motherboard. Connecting the wrong end can damage the fans.