



Product support: www.gmb.nl/service and/or helpdesk@gembird.nl


(ENG) To ensure safe handling of the product, follow the safety advice on: (DE/AT) Hinweise zum sicheren Gebrauch der Produkte finden Sie auf: (NL/BE) Voor een veilig gebruik van het product volgt u deze algemene veiligheidsaanwijzingen op: (ES) Para garantizar una manipulación segura de los dispositivos, siga las advertencias de seguridad disponibles en: (CZ) Abyste zajistili bezpečnou manipulaci s výrobkem, dočtěte si bezpečnostní pokyny na: (FR/BE) Pour garantir une manipulation sûre des appareils, suivez les consignes de sécurité sur: (IT) Per garantire una manipolazione sicura del prodotto, seguire i consigli di sicurezza su: (PT) Para garantir o manuseio seguro do produto, siga as recomendações de segurança em: (PL) Aby obchodzić się bezpiecznie z produktami, należy przestrzegać wskazówek dotyczących bezpieczeństwa: (RO) Pentru a asigura oare manipularii în condiții de siguranță a produsului, urmați recomandările de securitate de pe: (SK) Na zaistenie bezpečnej manipulácie so zariadeniami sa riadte bezpečnostnými pokynmi na: (SL) Za zagotavljanje varnega ravnanja z napravami, upoštevajte varnostna navodila, ki jih najдете na: (HR) Da biste osigurali sigurno rukovanje uređajima, pratite sigurnosne savjete na web-mjestu: (HU) A készülékek biztonságos kezelésének érdekében kövesse a biztonsági tanácsokat (BG) За да осигурите безопасна работа на устройствата, следвайте съветите за безопасност по-долу: www.gmb.nl/safety

[illegible]



VESA Compatible
75x75 100x100



Adjustable desk 3-display mounting arm (tilting), 17"-27", up to 7 kg



Note: If the display does not stop at your desired position, tighten the screws as shown.




To properly balance the arm with monitors mounted, adjust the spring tension using the supplied Allen Key as follows:

First, position and firmly hold the arm horizontally as shown. Ask for assistance should you require it.




If the arm **drops**, turn the adjustment screw counter-clockwise until it stays in a horizontal position.




If the arm **ris**es, turn the adjustment screw clockwise until it stays in a horizontal position.




CAUTION:
DO NOT over tighten the screws.



CAUTION: To avoid damage to monitors or mount, always keep the arm in a horizontal position while making adjustments. Again, ask for assistance if required.






A (x1)



B (x1)



C (x3)



D (x1)



E (x1)




F (x1)



G (x1)



H (x1)



I (x1)



J (x3)



K (x3)
M6x16



L (x1)
4mm



M (x1)
6mm



M-A (x4)
M4x12



M-B (x4)
M4x16



M-C (x4)
M5x12



M-D (x4)
M5x16




M-E (x4)
D5





M-F (x4)
Ø15xØ8x5

x3


1



2




Desktop with Existing Through-Hole.




10-40mm


OR




10-40mm



10-40mm



45-85mm




3


WARNING:

1. Firmly hold the two halves of the spring arm together and have another person cut Off the cable tie from around the spring arm.


2. Slowly release the pressure on the spring arm and allow it to gradually stretch to its full extension.



4



5



TOP

6

